



09/707452

COPY

Docket No.: TESSERA 3.0-051 FWC DIV  
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Joseph Fjelstad

Patent No.: 6,826,827 B1

Issued: December 7, 2004

For: FORMING CONDUCTIVE POSTS BY  
SELECTIVE REMOVAL OF CONDUCTIVE  
MATERIAL

Certificate  
FEB 28 2005  
of Correction

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION  
PURSUANT TO 37 C.F.R. § 1.323

Dear Sir:

Enclosed herewith are an original and one copy of a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the copy of the Certificate of Correction duly certified.

Dated: February 21, 2005

Respectfully submitted,

By

Marcus J. Millet  
Registration No.: 28,241  
LERNER, DAVID, LITTENBERG,  
KRUMHOLZ & MENTLIK, LLP  
600 South Avenue West  
Westfield, New Jersey 07090  
(908) 654-5000

Attorney for Applicant

02/23/2005 MGBREM1 00000003 121095 6826827

01 FC:1811 100.00 DA

**UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION**

PATENT NO. : 6,826,827 <sup>81</sup>  
DATED : December 7, 2004  
INVENTOR(S) : Joseph Fjelstad

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1, line 23, "and is adjacent" should read -- and adjacent --.  
Column 1, line 42, "foil of polyimide is provided" should read -- foil of polyimide, is provided --.  
Column 3, line 55, "device comprises" should read -- device which comprises --.  
Column 4, line 41, "post socket" should read -- post and socket --.  
Column 4, line 42, "post" should read -- post and socket. --.  
Column 4, line 47, "button hole" should read -- button and hole --.  
Column 5, line 24, "approximately, a 45° angle" should read -- approximately a 45° angle --.  
Column 6, line 8, "about p10%" should read -- about 5-10% --.  
Column 7, line 2, "shows a substantially" should read -- shows a post substantially --.  
Column 7, line 52, "gold-fin" should read -- gold-tin --.

MAILING ADDRESS OF SENDER:  
Marcus J. Millet  
LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP  
600 South Avenue West  
Westfield, New Jersey 07090  
545829\_I.DOC

PATENT NO. 6,826,827

No. of additional copies 0

MAR 02 2005